



Size	125	160	200
<b>Arnold Mat Automat</b>	<b>070 200 125</b>	<b>070 200 160</b>	<b>070 200 200</b>
Clamping force (kN)	40	50	50
A	410	570	570
B	515	675	675
C - 0,02	100	110	110
D	140	160	173
E	126	161	201
F	21	21	21
G	24	24	24
H	100	115	119
I	124	128	132
J + 0,02	90	115	111
K	190	230	230
L	50	60	60
M H7	20	20	20
N	40	50	63
U	54	68	68
V	13	13	13
W	125	140	140
X	195	300	300
Weight (kg)	35	70	93
<b>Clampings</b>	<b>125</b>	<b>160</b>	<b>200</b>
Clamping field O1	0-167	0-282	0-274
Clamping field O2	85-252	106-388	114-388
Clamping field O3	155-322	174-456	182-456
Clamping field O4	122-191	165-334	169-334
Clamping field O5	192-261	233-402	237-402
<b>Spare spindle</b>	<b>125</b>	<b>160</b>	<b>200</b>
Weight (kg)	870 000 125	870 000 160	870 000 160


**Clamping possibilities**




Clamping field O1




Clamping field O2



Clamping field O3



Clamping field O4



Clamping field O5

**Zero point system preinstallation**

This vice includes preinstallation for **O-MAK** zero point system.

