



Size	125	160
<b>Arnold MB2 Mechanical</b>	<b>060 121 125</b>	<b>060 121 160</b>
<b>Arnold MB2 Mechanical with power preset</b>	<b>060 131 125</b>	<b>060 131 160</b>
<b>Arnold MB2 Mechanical in 2 parts</b>	<b>060 123 125</b>	<b>060 123 160</b>
<b>Arnold MB2 Mechanical in 2 parts with power preset</b>	<b>060 133 125</b>	<b>060 133 160</b>
Clamping force (kN)	40	50
A	410	530
B	524	639
B (with power preset)	551	666
C -0.02	100	115
D	140	165
E	126	161
J +0.02	115	123
K	190	230
M H7	20	20
N	40	50
P	22	30
U	54	68
V	13	13
W	125	140
X	195	300
Weight (kg)	35	61
<b>Clampings</b>	<b>125</b>	<b>160</b>
Clamping field O1	0 - 254	0 - 310
Clamping field O2	80 - 334	120 - 430
<b>Spare spindle</b>	<b>125</b>	<b>160</b>
Arnold MB2 Mechanical	812 006 125	812 006 160
Arnold MB2 Mechanical with with power preset	813 006 125	813 006 160
Arnold MB2 Mechanical in 2 parts	812 016 125	812 016 160
Arnold MB2 Mechanical in 2 parts with power preset	813 016 125	813 016 160

### Clamping possibilities



Clamping field O1



Clamping field O2

### Zero point system preinstallation

This vice includes preinstallation for **O-MAK** zero point system.

